



THE GLIDING FEDERATION OF AUSTRALIA

BUILDING 130, WIRRAWAY ROAD, ESSENDON AIRPORT, VICTORIA 3041.

GFA/AD 217

SZD 20

19/11/1981

Issue 1

Sheet 1 of 2

AIRWORTHINESS DIRECTIVE GLIDERS/POWERED SAILPLANES

TYPES AFFECTED:

JANTAR SERIES GLIDERS

SZD - 37 x	-	Jantar 17
SZD - 37	-	Jantar 19
SZD 38	-	Jantar 1
SZD - 38 A	-	Jantar 1
SZD - 41	-	Jantar Std.
SZD - 41A	-	Jantar Std.
SZD - 41B	-	Jantar Std.

SUBJECT: Incorporation of inspection hole in the vertical fin.

BACKGROUND: This inspection hole allows the visual inspection of the elevator lever connection to the elevator control push rod.

REQUIRED ACTION:

- (1) Mark hole location on the righthand side of the fin, using the dimension shown on Fig 1.
- (2) Using a hole saw cut a 20 mm dia. hole.
- (3) Seal the hole edges and repair any local damage with polyurathane lacquer.

IMPLEMENTATION:

To be incorporated by the owner or any D.O.T. 1109 holder endorsed for FRP work.

COMPLIANCE DATE:

To be incorporated at or before next form 2 inspection at owner's discretion.

COMPLIANCE:

This A.D. is issued pursuant to Air Navigation Regulations under delegated authority from the Secretary of the Department of Transport Australia.

M.P. BURNS.
CHIEF TECHNICAL OFFICER AIRWORTHINESS
GLIDING FEDERATION OF AUSTRALIA



THE GLIDING FEDERATION OF AUSTRALIA

BUILDING 130, WIRRAWAY ROAD, ESSENDON AIRPORT, VICTORIA 3041.

BULLETIN No. BE-10/80 "JANTAR"

GFA/AD 217

SZD 20

19/11/1981

Issue 1

Sheet 2 of 2




Fig. 1.