

# THE GLIDING FEDERATION OF AUSTRALIA

BUILDING 130, WIRRAWAY ROAD, ESSENDON AIRPORT, VICTORIA 3041.

GFA/AD 244

ROLLADEN SCHNEIDER 22

Issue 1,

5.10.1982

Sheet 1 of 1

AIRWORTHINESS DIRECTIVE GLIDER/POWERED SAILPLANE

1FD 3-10-2018 E CERTIFICATE HOLDERS WEBSITE

TYPE AFFECTED:

LS3-17 (All serial Nos).

SUBJECT:

Amendment of Maintenance Manual.

BACKGROUND:

Manufacturers Technical Bulletin No. 3031 provides

Maintenance Manual amendments.

Exchange or add pages 0-2, 3-2, 4-3, 5-1, 12-1, 13-6, dated

1st October 1982. (Pages attached)

COMPLIANCE:

The requirements of this Airworthiness Directive are mandatory. This Directive is issued pursuant to Air Navigation Regulations

under the delegated authority from the Secretary of the

Department of Aviation.

M.P. BURNS.

CHIEF TECHNICAL OFFICER AIRWORTHINESS

GLIDING FEDERATION OF AUSTRALIA

Rolladen Schneider Flugzeugbau GmbH

Maintenance Manual

LS3-17

Page 0.2

Edition 1.12.80

## LIST OF PAGES

Page	Edition	Edition	Edition	Edition	Edition	Edition	Edition	Edition
0.1	1.12.79			. **				
0.2	1.12.79	·						2007 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
1.1	1.12.79							
	1 10 50							
2.1	1.12.79					•	-	
2.2	1.12.79					· · · · · · · · · · · · · · · · · · ·		
2.4	1.12.79							<u> </u>
2.5	1.12.79							
/						·		
3.1 3.2	1.12.79		-					
3.2	1.12.79	1.10.82						
	4 46 75							
4.1	1.12.79			·		<b>_</b>		·
4.2	1.12.79	1.10.82						
4.0	1016017	1,10,02						
5.1	1.12.79	1.10.82						
6.1	1.12.79			·	-			
6.2	1.12.79							
0.4	4 40 70							
8,1	1,12,79							
-								
10.1	1.12.79				•			
10.2	1.12.79							
	•					·		·
11.1	1.12.79							
11.2	1.12.79							
40.4	1 10 70	4 4- 00						
	1.12.79	1.10.82						
1606	1012017		1					
13.1	1.12.79							
13.2	1.12.79							
13.3	1.12.79 1.12.79 1.12.79							
13.4	1.12.79							
13.5	1.12.79							
15.6	1.10.82					-		
14.7	1.12.79							
14.3	1.12.79					:		
						•		
15.1	1.12.79							
16.1	1.12.79							

30. 08. 82 Leuk

Coprist: 1. 8. 82 Wagha

Rolladen Schneider Flugzeugbau GmbH

Maintenance Manual

LS3-17

Page 3.2

Edition 1.10.82

## LUBRICATION SCHEDULE


Lo	cation	Frequency	Lubricant
1.	Pins and matching holes of automatic couplings of flaps divebrakes	Before assembly	Water insoluble bearing grease or Grease containing Molybdenum
	17m outer wing panels 15m tips elevator	IM. Falls	*
*	Main pins and matching holes. Ball snap joints of ailerons.		***
2.	Landing gear, all joints and at rubber bearings	Once a year	Oil
3.	Landing gear, all metal parts	Once a year	Spray oil
4.	Bearings on flaps auto- matic couplings	Once a year	Water insoluble bearing grease or
5.	Dive brakes bevel gear	Once a year	Grease containing Molybdenum
6.	Tow release	See	Spray oil
7.	FAG-7H safety harness multiple-point buckle	Maintenance Instructions of Manufacturer	G 353- Aero Shell Grease 17

Edition: 1.10.82


## INSTALLATION OF INTERNAL SEALS FOR ATLERONS AND FLAPS


The following items are necessary: 2 supports for horizontal wing position
2 supports for vertical wing position
Plain surface of 3.8e x 0.3e m (12.5 x 1.e ft)
for control surfaces.

- 1. Gap between wing and control surface upper side must be at least 1 mm (0.038 in) wide in all positions. Enlarge smaller gap on wingside only using sanding paper grade 60 glued to 0.5 mm (0.020 in) thick sheet metal.
- Mark rear edge of wing on upper side of control surface using soft pencil, when fully deflected downward. Take control surface off with two persons.
- 3. Roughen gluing area on inside upper rear wing edge using sanding paper grade 60. Round sharp edge slightly (sanding paper grade 180) and blow off dust.



- 4. Clean gluing area at rear inner edge and on sealing tape with lead-free petrol. Lay sealing tape on table and stick adhesive film edge flush to sealing tape edge.
- 5. Mark rear gluing edge inside rear wing edge as fellows: 4 mm (e.157 in) ferward of rear edge from tip to 1 m (3.28 ft) outside root rib, from there increase distance continuously to 10 mm (e.394 in) at root rib.
- 6. Pull masking tape off prepared sealing tape and glue to inside rear wing edge along marked line. Press gluing temperarily.
- 7. Clean leading edge of control surface behind marked rear edge of wing with acetone, and second side of sealing tape.
- 8. Stick adhesive film to leading edge of control surface flush behind marking line.
- 9. Mount control surface to wing and extend fully downward. Pull sealing tape out of gap, pull masking tape off and lay sealing tape on adhesive film avoiding bracing or lateral displacement. Press adhesive film area temporarily using roller.
- 10. Cut surplus sealing tape along rear edge of adhesive film using sharp knive and straight edge.
- 11. Mask rear edge of sealing tape with white PVC tape to avoid warping.





Rolladen Schn	eider	1	·	Page 5-1
Flugzeugbau	GmbH	MAINTENANCE MANUAL	LS3-17	Edition 1.10.82

COMPONENTS LIFE / TBO

- 1. C.G. release Tost Europa G73: 36 months or 2000 starts ) or Tost Europa G72
- 2. Nose release Tost E75: 36 months or 2000 starts ) Tost E72
- 3. Safety harness Autoflug FAG-7H : 10 years from manufacturing date. ) (Before 1980 manufactured safety harnesses only 7 years)

Erstellt: 3 0. 08. 32 Lauk,

Ersetzt:

<sup>)</sup> See also Maintenance and Operating Instructions of manufacturers.

Rolladen	Schneider
Plugzeugh	au CmbH

Maintenance Manual

LS3-17

Page 12.1

Edition 1.10.82

#### MINIMUM EQUIPMENT

1. Airspeed Indicator Scale from 50 to 300 km/h (27-162 kts, 31-186 mph)

Colour markings:

red radial red radial red radial red radial yellow arc	250 km/h 234 km/h 203 km/h 162 km/h 160-250 km/h 85-160 km/h	135 kts 126 kts 110 kts 87 kts 86-135 kts 46-86 kts	155 mph 145 mph 126 mph 101 mph 99-155 mph 53-99 mph	and placard saying VNE up to	9800 19700 32800	ft
green arc	85-160 km/h	46-86 kts	53-99 mph			*5
yellow triangle	90 km/h	49 kts	56 mph		3.€	

- 2: Altimeter in ft.
- 3. Magnetic compass.
  - 4. Four piece seat belt harness.
  - 5. Seat cushion or parachute in compressed form should not be thinner than 80-100 mm (3-4 in).
  - 6. Checklist, Type placard, Weight and Balance plan and operating placards.
  - 7. LS3-17 Flight Manual.

#### In addition for CLOUD FLYING:

- 1. Turn and Bank Indicator or artificial horizon.
- 2. Variometer.

NOTE: The required minimum equipment must be certified for use in sailplanes.

#### INSTRUMENTATION

Required installed instruments approved during initial type certification:

Name Maker Type TSO-Standard Airspeed Indicator Winter 6FMS4-2 TSO C-2b

Altimeter Winter 4FGH 10 TSO-10b including AS 392C

Magnetic Compass Airpath G 2300 TSO C-7c

### MASTER EQUIPMENT LIST (Instruments)

## Basic Equipment Instruments

1. Approved Airspeed Indicators
Original certification was carried out using a Winter 6FMS4-2 airspeed indicator
with a range of 30 to 300 km/h, maximum permissible error ± 2%.
Any FAA approved airspeed indicator for use in aircraft with an effective range
of 300 km/h (162 kts, 186 mph) may be used, max. permissible error ± 2%.
Colour coding must be as follows:

red radial red radial yellow arc green arc white arc	250 km/h 234 km/h 203 km/h 162 km/h 160-250 km/h 85-160 km/h	46-86 kts 46-86 kts	53-99 mph 53-99 mph	and placard saying VNE up to	9800 ft 19700 ft 32800 ft
yellow triangle	90 km/h	49 kts	56 mph		

Geprüft: i. c. 62

Maple

Rolladen Schneider Flugzeugbau GmbH

Maintenance Manual

LS3-17

Page 13-6

Edition 1.10.82

Recommendations to maintenance and care of gelcoat surfaces according to paint manufacturer Lesonal's note dated 7.7.81

Suitable: Water with washing-up liquid added in recommended quantities, car polish with or without silicone.

Suitable with reservations: Tar remover based on petrol for cars. Alcohol, like spirit or isopropyl alcohol. Reservations are, that these liquids should only be used for wiping off, not for soaking with rags !

Unsuitable: Strong solvents and thinners, they may decompose gelcoat and cause local shrinking.

Completely unsuitable: Trichloroethylene, carbon tetrachloride or similar hydrocarbon chlorides. These liquids destroy the gelcoat.

Other mediums must be checked for suitability by Lesonal before use !

Warning: Sanded gelcoat shows distinctive weathering marks due to changes of temperature, ultra violet radiation and humidity unless regularly polished with hardwax.

3 0. 08. 62 Leuch Ersetzt: