

COMMONWEALTH OF AUSTRALIA  
DEPARTMENT OF TRANSPORT

AIRWORTHY ADVICE NOTICE GLIDERS.

G.F.A./AN 32  
Rolladen Schneider  
Technical Bulletin 3010

GLIDER TYPE AFFECTED: LS 3

SUBJECT: Flap handle detent.

ACCOMPLISHMENT: Optional.

REASON: A flap handle detent for flap positions 0 degrees and +5 degrees may be fitted to the left fuselage rim.

INSTRUCTIONS AND MATERIALS: See drawing 3BR-6 obtainable from the Manufacturer. Materials obtainable from manu/fctrs.


WEIGHT AND BALANCE: Negligible.

REMARKS: Modification by experienced person. Accomplishment should be checked by a C.of A. Inspector and signed in the log book.

CANCELLED

CANCELLED

DATE OF ISSUE: 3/11/78



DOUGLAS LYON

CHIEF TECHNICAL OFFICER AIRWORTHINESS.

CANCELLED