

AIRWORTHINESS DIRECTIVE

CANCELLED 9.02.2017
Refer Type Certificate Holders current data

TYPE AFFECTED: KR-03A Puchatek.

SUBJECT: Extension of service life to 5000 hours and Flight and Maintenance Manual amendments.

DOCUMENTATION: PZL Krosno Technical Bulletins BZ-12/KR-03A/91 and BE-23/KR-03A/92.

ACTION REQUIRED: As soon as practicable, but before August, 1992, the flight and maintenance manuals must be amended as follows:

For serial number 03-01 and onwards amend

The Flight Manual pages 0.1, 0.2, 0.3, 0.4, 1.2, 1.3, 2.4, 2.5, 2.6, 2.7, 2.8, 2.9, 2.10, 2.11, 2.12, 2.13, 4.4, 4.5, 4.8, 4.9, 5.2, 5.3.

The Maintenance Manuals pages 0.1, 1.1, 2.2, 3.9, 3.17, 4.1, 4.2, 4.3, 4.4, 4.5, 4.6, 4.7, 5.25, 5.30, 5.31, 5.33, 5.40, 5.41.

The Repair Manual pages 0.1, 4.3.

These pages are available from the GFA secretariate on request.

Once the amendments have been introduced the glider must be operated according to the new flight and maintenance manuals. This will allow operation of the glider to 5000 hours.

WEIGHT AND BALANCE: Not affected.

IMPLEMENTATION: Manual amendments may be incorporated by the owner.

COMPLIANCE: The requirements of this Airworthiness Directive are mandatory. This Directive is issued pursuant to the Australian Civil aviation Regulations under the delegated authority of the Civil Aviation Authority (CE042/90).

SIGNED: Pat Larcey

For and on behalf of:

CHIEF TECHNICAL OFFICER AIRWORTHINESS

THE GLIDING FEDERATION
OF AUSTRALIA