COMMONWEALTH OF AUSTRALIA

DEPARTMENT OF TRANSPORT

AIRWORTHINESS DIRECTIVE GLIDERS

GFA AD/135 SCHEMPP-HIRTH 4

TYPES AFFECTED:

Standard Cirrus

Standard Cirrus B

Standard Cirrus CSII - 75L

ACTION:

The enclosed pages of supplementary instructions are to be added to the Service Manual of the Sailplane.

Page 24 - Ground Handling

Pages 26 and 26A - Adjustment of the Air Brakes

Page 27 - Replacement of the wing attachment Attachment Ball Bearings

Pages 28 and 29 - Weight and Hinge Moment of the Control Surfaces.

ACCOMPLISHMENT:

Immediately.

COMPLIANCE:

This directive is mandatory.

This directive is issued pursuant to Air Navigation Regulations under the delegated authority of the Secretary of the Department of Transport.

(Douglas Lyon)

CHIEF TECHNICAL OFFICER AIRWORTHINESS

GLIDING FEDERATION OF AUSTRALIA

Date of Issue: 22nd March, 1979.